



# Technical Bulletin

**Date:** August 24, 2018

**Product Line:** Bambi

**Models:** Bambi Bucket 5566-HL9800


**Subject:** Large Tripline Design Change

## Background

Triplines failing immediately below the bullet assembly has been a recurring issue on large Bambi Buckets. The root cause is believed to be the cable flexing during take-off and landing. A new design allows the cable to freely pivot immediately after the bullet to eliminate this issue.

The new design is a direct replacement and does not require any additional modification.

Old Design		New Design	
Part #	Description	Part #	Description
005333	TRIPLINE, 5566-7590	013058	TRIPLINE, FLEX, 5566-7590
005336	TRIPLINE, HL4000-HL9800	013059	TRIPLINE, FLEX, HL4000-HL9800



## Recommendations

New triplines made by SEI will use the new design. Customers with the old design should continue to use those triplines if they have not encountered problems with them.





This Technical Bulletin is available on the SEI website:

<https://www.sei-ind.com/category/bambi-safety-bulletins/>

For further details, please contact the following SEI representatives.

## Contact

Alex Wutschnik, EIT  
Product Engineer, Aerial Firefighting Division  
604-946-3131 ext. 139  
[alexw@sei-ind.com](mailto:alexw@sei-ind.com)

Robert Button, P.Eng  
Product Engineer, Aerial Firefighting Division  
604-946-3131 ext. 423  
[robert@sei-ind.com](mailto:robert@sei-ind.com)