



# Technical Bulletin

**Date:** August 19<sup>th</sup>, 2016

**Product Line:** Bambi

**Models:** All model with Powerfill Snorkel

**Subject:** Introduction of Powerfill Quick Connect

## Background

SEI has developed a new style of Powerfill Snorkel that will supersede the standard bolt-on Powerfill Snorkels that many of our customers are familiar with. The new product has a new elbow and flange that couple together with Cam-Lock fittings. This allows customers to quickly and easily remove their Powerfill Snorkel from their bucket for storage, maintenance and also to interchange the system with other buckets that have the flange assembly.

This upgrade only affects the elbow and flange of the snorkel. An existing Snorkel can be upgraded to a Cam-Lock equipped snorkel by simply replacing these components. Upgrading to a new Cam-Lock equipped Snorkel or switching between the bolt-on and Cam-Lock style snorkels requires only basic hand tools and can be done in the field.

The bolt-on style Powerfill Snorkel will continue to be supported by SEI, but will no longer be sold as new.


## Recommendations

Customers interested in purchasing a new Powerfill Snorkel or upgrading their existing snorkels should review the following table to see what they will need to order:



**Bambi**  
**BUCKET**  
 Driven by innovation

**PARTS FOR CUSTOMERS WITH OLD SNORKEL SYSTEM**

012829	SNORKEL,CAMLOCK,RETROFIT,KIT	<ul style="list-style-type: none"> <li>• Pump elbow, camlock flange, and hardware</li> <li>• Upgrade existing pump and flange assembly</li> </ul>	
011197	FLANGE,4",CAMLOCK,FABN	<ul style="list-style-type: none"> <li>• Camlock flange only (no flapper valve)</li> <li>• Upgrade the flange assembly on a second bucket</li> <li>• Needs additional mounting hardware</li> </ul>	
011196	ELBOW,4",CAMLOCK,FABN	<ul style="list-style-type: none"> <li>• Camlock elbow only</li> <li>• Upgrade a second pump</li> </ul>	





**PARTS FOR CUSTOMERS WITH NO SNORKEL SYSTEM**



SEI Industries Ltd. 7400 Wilson Avenue, Delta, B.C. Canada V4G 1H3  
 T: 604.946.3131 [seisales@sei-ind.com](mailto:seisales@sei-ind.com) [www.sei-ind.com](http://www.sei-ind.com)



**Bambi**  
**BUCKET**  
 Driven by innovation

012830	POWERFILL,SNORKEL,CAMLOCK,KIT 2024,w/FLANGE	<ul style="list-style-type: none"> <li>• Pump and flange assembly with flapper valve</li> <li>• New bucket installation</li> <li>• Old bucket that does not have a snorkel</li> </ul>	
012831	POWERFILL,SNORKEL,CAMLOCK,KIT 2226,w/FLANGE		
012832	POWERFILL,SNORKEL,CAMLOCK,KIT 2732,w/FLANGE		
012833	POWERFILL,SNORKEL,CAMLOCK,KIT 3542,w/FLANGE		
012834	POWERFILL,SNORKEL,CAMLOCK,KIT 4453,w/FLANGE		
013019	INSTALL,POWERFILL,KIT,2024-2226	<ul style="list-style-type: none"> <li>• Shortened battens, fabric and tools required for installation</li> <li>• Customer installation on bucket that does not have a snorkel</li> </ul>	
013020	INSTALL,POWERFILL,KIT,2732		
013023	INSTALL,POWERFILL,KIT,3542		
013024	INSTALL,POWERFILL,KIT,4453		
012835	PUMP,POWERFILL,SNORKEL,CAMLOCK 2024,NO FLANGE	<ul style="list-style-type: none"> <li>• Pump unit only</li> <li>• Spare pump</li> </ul>	
012836	PUMP,POWERFILL,SNORKEL,CAMLOCK 2226,NO FLANGE		
012837	PUMP,POWERFILL,SNORKEL,CAMLOCK 2732,NO FLANGE		
012838	PUMP,POWERFILL,SNORKEL,CAMLOCK 3542,NO FLANGE		
012839	PUMP,POWERFILL,SNORKEL,CAMLOCK 4453,NO FLANGE		
012840	FLANGE,SNORKEL,CAMLOCK,ASSY	<ul style="list-style-type: none"> <li>• Flange assembly with flapper valve</li> <li>• Extra flange assembly for a second bucket</li> </ul>	



This Technical Bulletin is available on the SEI website. <http://www.sei-ind.com/resources/manuals>

For further details, please contact the following SEI representatives.

### Contact

Shawn Bethel  
Division Manager, Firefighting Division  
604-946-3131 ext. 119  
[shawn@sei-ind.com](mailto:shawn@sei-ind.com)

Robert Button  
Product Engineer, Firefighting Division  
604-946-3131 ext. 423  
[robert@sei-ind.com](mailto:robert@sei-ind.com)